



BUILDING FEATURES


- 601,417 SF freestanding concrete tilt-up, industrial distribution/ manufacturing building
- Situated on 31.32 acre site
- Cross dock configuration
- 185' and 150' deep, secured truck courts
- 50' x 52' column spacing (typical)
- 30' 32' minimum clear height
- Knock-out concrete wall panels for 80 additional dock-high doors

- 3,000 Amps, 277/480 volt, 3 phase power (expandable)
- ESFR sprinkler system in warehouse
- 4 sets of men's and women's restrooms
- Security guardhouse, 3 gates,
 video cameras, and full perimeter
 fencing

LOCATION HIGHLIGHTS


- Otay Mesa/Tijuana region provides abundant skilled labor pool
- San Diego-Baja Bi-National Region encompasses over \$25 Billion in annual trade and 6,000,000 residents
- Completion of State Route 905 in 2012 provides direct freeway access and visibility
- Immediate access to I-5, I-805 and SR 125 (South Bay Expressway)
- Cross Border Terminal is 1 mile away

- Zoned OMDD-I, Otay Mesa
 Development District-Industrial, City of San Diego
- Direct access to 905 freeway and 125
 Toll Road
- Located adjacent to the World's busiest land border crossing and Tijuana's 500 maquiladora manufacturing plants










*Not to scale


SUITE FEATURES

SUITE 100

- ±94,315 SF End unit (5% office / warehouse remaining balance)
- 9 Dock high loading doors
- 1 Grade level loading door with ramp
- ±30' 32' Clear height

- Trailer Parking Available
- Available June 1, 2024
- Lease rate: \$1.20/SF/Mo. Net of Expenses
- NNN's = \$.32/SF









ROB HIXSON, SIOR

Senior Vice President Lic. 00944946 +1 619 696 8350

rob hivson@chre com

BILL DOLAN

Senior Vice President Lic. 01188240 +1 858 546 4678

bill.dolan@cbre.com

CBRE

BRANT ABERG, SIOR

Vice Chairman Lic. 01773573 +1 858 546 5464

brant.aberg@cushwake.com



© 2023 CBRE, Inc. All rights reserved. This information has been obtained from sources believed reliable, but has not been verified for accuracy or completeness. Any projections, opinions, or estimates are subject to uncertainty. The information may not represent the current or future performance of the property. You and your advisors should conduct a careful, independent investigation of the property and verify all information. Any reliance on this information is solely at your own risk. CBRE and the CBRE logo are service marks of CBRE, Inc. and/or its affiliated or related companies in the United States and other countries. All other marks displayed on this document are the property of their respective owners. Photos herein are the property of their respective owners and use of these images without the express written consent of the owner is prohibited.